

HP Elitedesk 800G2 Dual Monitor, aber wie bzw. was fehlt

Beitrag von „GoodBye“ vom 2. Dezember 2021, 21:22

[MrWeb](#)

"Dual monitors works. Patching has been done using hackingtool. HotPlugging a monitor is not required. The following patch has been applied"

Code

1. WhateverGreen: weg @ (DBG) agdpmod using config vit9696
2. WhateverGreen: igfx @ (DBG) patching framebufferId 0x19120000 connector [1] busId: 0x05, pipe: 9, type: 0x00000400, flags: 0x00000187
3. WhateverGreen: igfx @ (DBG) patching framebufferId 0x19120000 connector [2] busId: 0x06, pipe: 10, type: 0x00000400, flags: 0x00000187
4. WhateverGreen: igfx @ (DBG) patching framebufferId 0x19120000 connector [3] busId: 0x04, pipe: 10, type: 0x00000400, flags: 0x00000187
5. WhateverGreen: igfx @ (DBG) patching framebufferId 0x19120000 connector [-1] busId: 0x00, pipe: 0, type: 0x00000001, flags: 0x00000020
- 6.
7. Patch
- 8.
9. General > Devices/Properties
10. General > Connectors
11. General > Auto Detect Changes
12. Advanced > FB Port Limit 3
13. Device Id: 0x1912: Intel HD Graphics 530

Alles anzeigen

Das schon gelesen ? ist zwar Tower, könnte aber zielführend sein, allerdings crashed der Framebuffer manchmal beim Boot....

<https://github.com/sakoula/HP-EliteDesk-800-G2-6700>

seltener Weise habe ich 2 unterschiedlich Rückansichten gefunden, einmal mit 2 DP Nebeneinander und einmal übereinander ?

Wobei der Tower anscheinend die DP PORTS NEBENEINANDER HAT ?

