

Problem with booting MacOs Monterey.

Beitrag von „5T33Z0“ vom 12. Dezember 2021, 22:29

[oyku](#)

!\\ Sierra 10.12 dropped support for old Broadcom BCM431x and BCM4321 cards. There is no workaround, they have to be replaced. !\\

<https://osxlatitude.com/forums...-cards-2-sierra-monterey/>