

Huananzi x79 Dual CPU C602 Board & DDR3 RAM - Hackintosh Monterey 12.0/Windows 11 DevBeta mit OpenCore 0.7.0

Beitrag von „robcodemax“ vom 15. Dezember 2021, 03:51

[Zitat von haingo](#)

I still meet the same panic. Please find in the attachment my EFI folders utilizing both of your DSDT files to see if I have configured anything wrong.

Did you try to use my EFI Folder?

Please use my EFI Folder just remove the UT Map.kext and use your UTBkext.map. You can create this in windows using USBToolbox

Also use your SSDT-PMC and SSDT-PLUG created using SSDTTime

Please use my EFI Folder and only change the following. Rest keep it as is

In ACPI

SSDT-PMC (Create using Windows ssdttime)

SSDT-PLUG (Create using Windows ssdttime)

DSDTFULLPATCHED

and remove my SSDT-PM-ROBERT-2021 (No need of this while installing) You can create your SSDT-PM later using ssdtprgen method