

Big Sur auf i5 2500k (Sandy Bridge)

Beitrag von „Max“ vom 15. Dezember 2021, 15:26

[Furcate](#)

Hier die Fehler:

Code

1. OCS: Missing key Base, context <Patch>!
2. OCS: Missing key BaseSkip, context <Patch>!
3. OCS: Missing key SyncTableIds, context <Quirks>!
4. OCS: Missing key ForceBooterSignature, context <Quirks>!
5. OCS: Missing key ResizeAppleGpuBars, context <Quirks>!
6. OCS: Missing key ProvideCurrentCpuInfo, context <Quirks>!
7. OCS: Missing key CustomKernel, context <Scheme>!
8. OCS: Missing key Flavour, context <Entries>!
9. OCS: Missing key AllowToggleSip, context <Security>!
10. OCS: Missing key Flavour, context <Tools>!
11. OCS: Missing key Flavour, context <Tools>!
12. OCS: Missing key Flavour, context <Tools>!
13. OCS: No schema for AdviseWindows at 0 index, context <Generic>!
14. OCS: Missing key AdviseFeatures, context <Generic>!
15. OCS: Missing key ResetTrafficClass, context <Audio>!
16. OCS: Couldn't get array serialized at 0 index!
17. OCS: Couldn't get array serialized at 1 index!
18. OCS: Couldn't get array serialized at 2 index!
19. OCS: Couldn't get array serialized at 3 index!
20. OCS: Couldn't get array serialized at 4 index!
21. OCS: Couldn't get array serialized at 5 index!
22. OCS: No schema for KeyMergeThreshold at 2 index, context <Input>!
23. OCS: Missing key GopPassThrough, context <Output>!
24. OCS: No schema for AppleEvent at 3 index, context <ProtocolOverrides>!
25. OCS: Missing key AppleEg2Info, context <ProtocolOverrides>!
26. OCS: Missing key ActivateHpetSupport, context <Quirks>!
27. OCS: Missing key EnableVectorAcceleration, context <Quirks>!
28. OCS: Missing key ForceOcWriteFlash, context <Quirks>!
29. OCS: Missing key ForgeUefiSupport, context <Quirks>!

30. OCS: Missing key ReloadOptionRoms, context <Quirks>!
31. OCS: Missing key ResizeGpuBars, context <Quirks>!
32. OCS: Missing key AppleInput, context <UEFI>!
33. Serialisation returns 32 errors!
- 34.
35. ACPI->Add[0]->Path has filename suffix other than .aml and .bin!
36. CheckACPI returns 1 error!
- 37.
38. Booter->Quirks->ProvideCustomSlide is enabled, but OpenRuntime.efi is not loaded at UEFI->Drivers!
39. Booter->Quirks->EnableWriteUnprotector is enabled, but OpenRuntime.efi is not loaded at UEFI->Drivers!
40. CheckBooter returns 2 errors!
- 41.
42. Lilu.kext is loaded at Kernel->Add[0], but DisableLinkeditJettison is not enabled at Kernel->Quirks!
43. Kernel->Add[5]->PlistPath does NOT contain .plist suffix!
44. Kernel->Add[6] discovers SMCProcessor.kext, but its ExecutablePath () or PlistPath (Contents/MacOS/SMCProcessor) is borked!
45. Kernel->Add[6]->PlistPath does NOT contain .plist suffix!
46. Kernel->Add[7] discovers SMCSuperIO.kext, but its ExecutablePath () or PlistPath (Contents/MacOS/SMCSuperIO) is borked!
47. CheckKernel returns 5 errors!
- 48.
49. UEFI->Quirks->RequestBootVarRouting is enabled, but OpenRuntime.efi is not loaded at UEFI->Drivers!
50. CheckUEFI returns 1 error!
- 51.
52. Completed validating /Users/maxthone/Downloads/OpenCore-0-3/Utilities/ocvalidate/config.plist in 4 ms. Found 41 issues requiring attention.

Alles anzeigen