

Huananzi x79 Dual CPU C602 Board & DDR3 RAM - Hackintosh Monterey 12.0/Windows 11 DevBeta mit OpenCore 0.7.0

Beitrag von „robcodemax“ vom 16. Dezember 2021, 15:10

Guys those who are having X79 Motherboard and having

1. Issue with HT
2. Unable to boot to Mac

Just use my EFI and it will boot without any issue. This EFI will work for both Dual CPU and Single CPU Board.

1. Please add you own Platform Info
2. Also please add your UTBMap.kext file created using [USBToolbox](#) from windows(Use the windows.exe from there). Please don't use my UTBMap.kext it may not work.
3. **Please don't change any settings in config. It will go smoothly.**
4. Boot

Enjoy....!!!

If PowerManagement is not working then do the following

1. Create SSDT-PM using ssdtprgen method
2. Create SSDT-PMC, SSDT-PLUG from windows using SSDTTime.exe
3. So you should have SSDT-PM, SSDT-PMC, SSDT-PLUG and SSDT-X9 in ACPI. Don't use SSDT-UNC, its already included in the SSDT-X79.

Enjoy your PowerManagement

Once again please don't change anything in the config other than what is mentioned above

Audio:

If you want to get the audio (ALC 892) working then you need to patch DSDT. Mine is working with DSDT Patching. It was not working out of the box.