

# Huananzi x79 Dual CPU C602 Board & DDR3 RAM - Hackintosh Monterey 12.0/Windows 11 DevBeta mit OpenCore 0.7.0

Beitrag von „robcodemax“ vom 17. Dezember 2021, 09:14

[Zitat von haingo](#)

Actually, I have been using your latest EFI with USBMap.kext is the only modification to get USB keyboard and mouse work (along with turning off XHCI hand-off and EHCI hand-off). I mentioned above that I cannot boot with dual CPU. The screen gets stuck at

```
[ EB | #LOG:EXITBS:START ]
```

With single CPU, I can pass this point.

What happens when you try the EFI from the author of this thread?