

Huananzi x79 Dual CPU C602 Board & DDR3 RAM - Hackintosh Monterey 12.0/Windows 11 DevBeta mit OpenCore 0.7.0

Beitrag von „robcodemax“ vom 18. Dezember 2021, 04:24

Now create SSDT-PMC, SSDT-PLUG, and SSDT-PM and place it in your ACPI folder

[Zitat von haingo](#)

I've got Monterey installed now but there are several issues:

1. PC restarts during boot process before reaching Apple logo screen at very high rate. Let's say I can boot into Monterey only once in 3-4 tries.
2. CPU power management is not working
3. Audio is not working