

Huananzi x79 Dual CPU C602 Board & DDR3 RAM - Hackintosh Monterey 12.0/Windows 11 DevBeta mit OpenCore 0.7.0

Beitrag von „robcodemax“ vom 18. Dezember 2021, 07:16

[Zitat von haingo](#)

Yes. Here is my EFI with config.plist and SSDT files

Now try using only SSDT-PM, SSDT-PMC, SSDT-PLUG and SSDT-X79 and check and let me know. Disable all other SSDT. It should work now

I have attached your modified config.plist