


Huananzi x79 Dual CPU C602 Board & DDR3 RAM - Hackintosh Monterey 12.0/Windows 11 DevBeta mit OpenCore 0.7.0

Beitrag von „haingo“ vom 18. Dezember 2021, 12:42

I've got PM working 😁



The problem lies in AppleIntelCPUPowerManagement patch. I take it from a guy [here](#). The two issues left are: random restart and audio 😊