

HP Envy 15-ep0080ng / OpenCore 0.6.2 / i9-10885H OctaCore / 32GB RAM

Beitrag von „Eugene2878“ vom 7. Februar 2022, 00:36

[Zitat von EdD1024](#)

I use an app, Brightness Slider.

I hope you not using your ssdt_data.aml, cause it is wrong. It must be _SB.PR00 not _PR.PR00
you injecting plugintype = 1 for cpu.