

# Monterey Installation Hilfe

Beitrag von „badbrain“ vom 13. Februar 2022, 17:05

Zitat

- **Note:** With macOS 10.15.5 and newer, there seems to be a lot of issues with black screen using `07009B3E`, if you get similar issues try swapping to `00009B3E`

We also add 2 more properties, `framebuffer-patch-enable` and `framebuffer-stolenmem`. The first enables patching via `WhateverGreen.kext`, and the second sets the min stolen memory to 19MB. This is usually unnecessary, as this can be configured in BIOS(64MB recommended) but required when not available.

```
framebuffer-patch-enable Data 01000000
```

```
framebuffer-stolenmem Data 00003001
```