

# Neues Projekt: HP-250 G8 (i5-1035G1) - Touchpad will noch nicht

Beitrag von „RenStad“ vom 4. April 2022, 14:53

Da das Pad nun gar nichts macht, ist Deine Überlegung sicher nachvollziehbar. Aber das wäre wirklich zu einfach. Dies hat zwar auch zwei Tasten, aber Einschalten muss man das Touchpad nicht, weder in Windows, noch in Linux.

EDIT:

Ich habe mal die Meldung beim Booten in Ruhe angeschaut. VoodooI2C meldet folgendes:

- VoodooI2CPCILakeController::pci8086,34e8 Starting I2C Controller
- VoodooI2CPCILakeController::pci8086,34e8 Set PCI power state D0
- VoodooI2CPCILakeController::pci8086,34e8 Current CPU is Comet lake or Ice Lake, patching...
- VoodooI2CPCILakeController::pci8086,34e8 Publishing nub
- VoodooI2CControllerDriver::pci8086,34e8 Probing controller
- VoodooI2CControllerDriver::pci8086,34e8 Found valid Synopsys components, continuing with initialisation
- VoodooI2CControllerNub::pci8086,34e8 SSCN not implemented in ACPI Tables
- VoodooI2CControllerNub::pci8086,34e8 FNCN not implemented in ACPI Tables
  
- VoodooI2CControllerDriver::pci8086,34e8 Warning: Error getting bus config, using defaults where necessary
- VoodooI2CControllerDriver::pci8086,34e8 Publishing device nubs

Weiß jemand, was SSCN und FNCN hier bedeutet.?