

Mac OSX mit AMD Prozessor

Beitrag von „fabiosun“ vom 8. April 2022, 09:03

[AymanKraus](#)

if you decide to use OCAT app you have to read carefully AMD CPU configuration guide

B550 EFI is based on a 12 cores cpu.

You have to do a minimal change in kernel patches section

As said above MSI board could be problematic with latest bios , new 5xxx CPU and Monterey..some success with latest X570 board..often is not possible to proceed fine!