

Kein Ton, kein Drucker nach Installation

Beitrag von „Norderstedter“ vom 13. April 2022, 10:49

Die Pin Configuration lässt sich nicht vergrößern...

The screenshot shows the 'Audio Info' section of Mac OS System Information. The 'Pin Configuration' table is as follows:

ID	PinDefault	Device	Connector	Port	Brace Location	Geometric Location	Color	S	P	EAPD	
27 (Dv18)	C221950	Out	HP Out	1/8" Stereo/Mono	Jack	External	Front	Green	5	0	0x2
30 (Dv1E)	0145103	Out	S/PDIF Out	Optical	Jack	External	Rear	Black	7	0	-
24 (Dv18)	05A1302C	In	Mic In	1/8" Stereo/Mono	Fixed	Internal	N/A	Black	1	0	-

The bottom part of the screenshot shows a larger view of the Pin Configuration table with the following data:

ID	PinDefault	Device	Connector	Port	Brace Location	Geometric Location	Color	S	P	EAPD	
24 (Dv18)	05A1302C	In	Mic In	1/8" Stereo/Mono	Fixed	Internal	N/A	Black	1	0	-
28 (Dv1A)	2181320	In	Line In	1/8" Stereo/Mono	Jack	External	Rear	Black	2	0	-
25 (Dv19)	02A79980	In	Mic In	1/8" Stereo/Mono	Jack	External	Front	Pink	8	0	-
13 (Dv1T)	00100000	Out	Line Out	Unknown	No Connect...	External	N/A	UNKN...	15	0	-
25 (Dv19)	02A79980	In	Mic In	1/8" Stereo/Mono	Jack	External	Front	Pink	8	0	-
23 (Dv17)	400000F0	Out	Line Out	Unknown	No Connect...	External	N/A	UNKN...	15	0	-
17 (Dv1T)	400000F0	Out	Line Out	Unknown	No Connect...	External	N/A	UNKN...	15	0	-