

Anfragen zu HWC: OOB BCM94360NG NGFF BROADCOM KARTE

Beitrag von „Der_Sparsame“ vom 28. Mai 2022, 16:31

Hallo Jungs.

Habe heute die BMC94360NG eingebaut. Bei mir wird der Kext BlueToolFixup allerdings nicht geladen. Bluetooth bricht auch ständig ab.

Andere Kexte zur Karte habe ich keine im System. macOS Monterey 12.4.

Edit: Ich habe die **USB-Ports** nochmal neu konfiguriert, denn der Connector stand nicht auf **Intern** sondern auf **USB3**. Den **BlueToolFixUp** wieder rausgeworfen. Dann das Bluetoothmodul mit **sudo pkill bluetoothd** zurückgesetzt. Und in der /Library/Preferences/ die **.com.apple.bluetooth.plist** gelöscht. Dann **NRAM** gelöscht. Neustart und siehe da, die Karte läuft wie gewünscht und in der "Werbung" versprochen!

Eintrag in der config.plist:

Key	CPUPowerManagement.plist	V15.0	Contents/MacOS/CPUPowerM1.plist	Contents/Info.plist
Key	BluetoothFixup.kext	V0.4.2	Contents/MacOS/BluetoothFixup.kext	Contents/Info.plist
Key	SMCBluetoothManager.kext	V1.2.8	Contents/MacOS/SMCBluetoothManager	Contents/Info.plist
Key	SMCBluetooth.kext	V1.2.8	Contents/MacOS/SMCBluetooth.kext	Contents/Info.plist
Key	SMCProcessor.kext	V1.2.8	Contents/MacOS/SMCProcessor	Contents/Info.plist
Key	SMCSuperIO.kext	V1.2.8	Contents/MacOS/SMCSuperIO	Contents/Info.plist
Key	MacbookP22Controller.kext	V0.2.7	Contents/MacOS/MacbookP22Controller	Contents/Info.plist

Systeminformation macOS:



Hackintool USB Devices (Alt):

Name	Location ID	Port	Connector	Dev Speed	Device
HS01	0x14100000	Dx01	USB3	?	Unknown
HS02	0x14200000	Dx02	USB3	?	Unknown
HS03	0x14300000	Dx03	USB3	?	Unknown
HS04	0x14400000	Dx04	USB3	?	Unknown
HS05	0x14500000	Dx05	USB3	?	480 Mbps EasyCamera
HS07	0x14600000	Dx07	USB3	?	12 Mbps BRCM20702 Hub
SS02	0x14700000	Dx0E	USB3	?	Unknown
SS03	0x14800000	Dx0F	USB3	?	Unknown

Hackintool geladene Kexts:

Name	Installed	Current	Download	Replaced By	Description
AppleALC	1.2.0	1.2.1			An open-source kernel extension enabling native macOS HD audio for non-officially-
CPULimit	1.2.0	1.2.0			A kext/plugin for dynamic power management data injection.
LibX	1.6.0	1.6.0			An open-source kernel extension bringing a platform for arbitrary kext, library and pr-
RealtekCardReader	0.9.6	0.9.6			An unofficial macOS kernel extension for Realtek PCIe/USB-based SD card readers.
RealtekRTL8111	2.4.2	2.4.2			An open-source driver for the Realtek RTL8110/8168 family of network controllers.
VirtualSMC	1.2.0	1.2.0			Advanced Apple SMC emulator in the kernel. Requires LibX for full functionality.
VirtualSMC2	1.1.0	1.1.0			An open-source trackpad aggregator kernel extension providing Magic Trackpad 2 e...
VirtualPS2Controller	2.2.0	2.2.0			Contains updated Virtual PS/2 Controller, improved Keyboard & Synaptics TouchPa...
WhateverGreen	1.5.0	1.5.0			LibX plugin providing patches to select GPUs on macOS, requires LibX 1.2.0 or newer.

UPDATE DER USB-PORT-KEXT:

Type	Name	Location ID	Port	Connector	Dev Speed	Device
UHC	HS01	0x14100000	Dx01	USB3	?	Unknown
UHC	HS02	0x14200000	Dx02	USB3	?	480 Mbps
UHC	HS03	0x14300000	Dx03	USB3	?	480 Mbps
UHC	HS04	0x14400000	Dx04	USB3	?	480 Mbps iPhone
UHC	HS05	0x14500000	Dx05	USB3	?	480 Mbps EasyCamera
UHC	HS07	0x14600000	Dx07	Internal	?	12 Mbps BRCM20702 Hub
UHC	SS02	0x14700000	Dx0E	USB3	?	5 Gbps USB Extreme Pro
UHC	SS03	0x14800000	Dx0F	USB3	?	5 Gbps ADATA USB Flash Drive