

# Ryzen 5 5600x und RX 6900 xt

Beitrag von „fabiosun“ vom 19. Juni 2022, 19:54

[Hecatomb](#) Also your EFI miss core count exact number for his CPU

B800

BA00

BA00

should be

B806

BA06

BA06

if his cpu is a 6 cores

attached one EFI built with OCAT default preset for B550

Some stuff to check in bios

UEFI on

CSM Off

4G on if present

if not , to add npci=0x2000 on config plist boot-arg