

Dell Optiplex 3040 Stuck

Beitrag von „OSX-Einsteiger“ vom 20. Juli 2022, 21:43

Mache aus der 00080000 daraus 00040000 für Display-Port

```

x [root@hypervisor ~]#
└─ Add
  └─ Pulverizer[2439/Pulv[2432].dvd]
    └─ AAFI_ig platform-id data 00000000
    └─ AAFI_ig name string Harnesig 2.0
    └─ device-id data 12000000
    └─ device-name string VSA compatible controller
    └─ enable-hibernation-file data 00000000
    └─ harnesig-ig-cs0-enable data 00000000
    └─ harnesig-ig-cs0-gpio data 12000000
    └─ harnesig-ig-cs0-type data 00000000
    └─ harnesig-ig-cs1-enable data 00000000
    └─ harnesig-ig-cs1-gpio data 00000000
    └─ harnesig-ig-cs1-type data 00000000 ←
    └─ harnesig-ig-cs2-enable data 00000000
    └─ harnesig-ig-cs2-gpio data 12000000
    └─ harnesig-ig-cs2-type data 00000000 ←
    └─ harnesig-ig-num data 00000000
    └─ harnesig-ig-pch-enable data 00000000
    └─ harnesig-ig-pch-gpio data 00000000
    └─ harnesig-ig-pch-type data 00000000
    └─ harnesig-ig-pch-gpio data 00000000
    └─ model string Intel HD Graphics 530

```