

Ryzentosh - Auros B550i PRO AX - "3,6GHz Unbekannt" fix ?

Beitrag von „user1_“ vom 8. August 2022, 15:29

[Zitat von fabiosun](#)

could you try to disable feature unlock kext and SMCADProcessor kext and innie.kext?
then reset Nvram again and see?

and also from terminal:

```
sysctl -n machdep.cpu.brand_string
```

nothing changed.

```
user@users-iMac-Pro ~ % sysctl -n machdep.cpu.brand_string
```

AMD Ryzen 5 3600 6-Core Processor

```
user@users-iMac-Pro ~ %
```

I ask like n newb 😊

possible to use bootarg revcpuname=AMD Ryzen 5 3600 6-Core Processor

?