

Erledigt

Hardware-Kompatibilität | Intel-Setup mit Thunderbolt 3/4 für rund 2'500€

Beitrag von „fabiosun“ vom 9. August 2022, 19:08

[Zitat von Flynn LG](#)

Thanks for your post about the Titan Ridge! Your pictures are quite interesting, because I didn't think that you modified your flashing device to output 3,3V (you checked it with the multimeter but didn't modified anything). Am I right or did you do it?

Yes there is a piece you can see in my photo I have mounted, then I have checked their voltage..it was 3.3....flashed without any problem and .. I am not able to build a bridge on the flasher chip as I see someone must do to achieve correct voltage

I was lucky because if my multimeter had shown 5 v..I would have to stop my try because I wouldn't be able to solder that wire! 😊😊