

# AQUANTIA AQC107 Monterey 12.5.1 läuft nicht

Beitrag von „thusis“ vom 9. September 2022, 13:43

Dank dir viel mals at kaneske. Hab Disableiomapper=false, Forceaquantia=true und in Bios Vt-d=enabled. Also nach zig mal Networkinterface.plist etc. löschen funktioniert die ACQ 107 nun in 12.5.1 sauber unter en=0. Allerdings funzt die Fenvie 919 nicht mehr wegen VT-d. Wie kireg ich das gebacken?

Liebe Grüsse

Ja ioreg könnt ich, aber nun liegt wohl an dmar. Aber da weiss ich nicht was ich machen muss.

Eine Idee?

Solved ACQ 107 und Fenvie T919 funktionieren beide:

Folgende Lösung hab ich in einem anderen Forum gefunden.

1. Open MaciASL,
2. File > New from ACPI > DMAR
3. Remove the following text (Note: there are two 'Reserved Memory Regions' so only remove this one.)
4. Remove the following: See picture attached
5. File > Save as > "DMAR.aml"
6. Add "DMAR.aml" to your ACPI folder in Open Core,
7. In your config > Add an entry for "DMAR.aml" in your ACPI > Add section.
8. Add and entry in ACPI > Delete with the following: see picture attached
9. Use Open Core Configurator as OCAT you need to put in HEX Values for the delete section for DMAR. In Open Core there is a drop down menu to choose DMAR in Table Signature

Edit Fenvi Wifi funzt, bluetooth macht Probleme. Das liegt aber vermutlich an fehlender Unterstützung von Bluetoot.kext. Der USB Port an der Fenvie ist auf internal gestellt