

Erledigt

# Gigabyte B550 AORUS PRO AC Bios Settings / DDR Speichersteckplatz Problem

Beitrag von „fabiosun“ vom 25. September 2022, 10:44

[avus90](#) which config.plist and kexts are you using? SMBIOS? mapped memory in config? and so on! 😊

Edit:

256 GB Installed

Your Mac contains 12 memory slots, 4 of which are installed with a 3200 MHz DDR4 memory module.

Slot	Bank/Tag	Bank/Locator	Serial/Locator	Manufacturer	PartNumber	Size
1	0040070	BANK 7	Channel0-DIMM0	Viper Patrol	CMR4040M033000C16	32 GB
2	0240070	BANK 8	Channel0-DIMM1	Viper Patrol	CMR4040M033000C16	32 GB
3	0240070	BANK 9	Channel0-DIMM2	Viper Patrol	CMR4040M033000C16	32 GB
4	0240070	BANK 10	Channel0-DIMM3	Viper Patrol	CMR4040M033000C16	32 GB
5		BANK 11	Channel0-DIMM4	NO DIMM		
6		BANK 12	Channel0-DIMM5	NO DIMM		
7	0240070	BANK 6	Channel0-DIMM6	Viper Patrol	CMR4040M033000C16	32 GB
8	0240070	BANK 5	Channel0-DIMM7	Viper Patrol	CMR4040M033000C16	32 GB
9	0240070	BANK 4	Channel0-DIMM8	Viper Patrol	CMR4040M033000C16	32 GB
10	0240070	BANK 3	Channel0-DIMM9	Viper Patrol	CMR4040M033000C16	32 GB
11		BANK 2	Channel0-DIMM10	NO DIMM		
12		BANK 1	Channel0-DIMM11	NO DIMM		

Upgrade Instructions...

Done

Automatic  
Keep Data such as "DataHub"

Custom Memory  
Custom Memory  
Custom Memory

without restrictevents.kext with custom memory mapping (errors in full slot number (4 instead 8, but graphics representation is good)