

Gigabyte Designware X299 Freeze nach Bios Update

Beitrag von „Steverayxx“ vom 31. Oktober 2022, 09:45

overclock an oder aus macht keinen Unterschied beim Booten oder den akuten Abstürzen im neuen BIOS (Ohne übertakten ist der Rechner nicht wirklich hilfreich, da Logics Bottleneck die Single Core Performance ist, native ist der 10980 xe 3GHz, übertaktet war auf 4,8)

CFG Lock gibt es im BIOS nicht, falls du das meinst die anderen wichtigsten Settings sind hier:

Extreme Memory Profile: (X.M.P): **Off**

CSM Support : **disabled**

Advanced CPU Core Settings

Turbo Boost: **native**

Hyper-Threading Technology: **Auto**

Intel Turbo Boost Max Technology 3.0 : **Native**

VT-d : **disabled**

Intel Speed Shift Technology : **Enabled**

CPU EIST: **disabled**

Turbo Boost: **Auto**

C States Control: **enabled**

CPU Enhanced Halt (C1E): **Auto**

C6/C7 State Support: **auto**

Package C State limit: **C6 retention state**

Settings IO Ports:

Above 4G Decoding: **enabled**

Resize bar support: **disabled**

Thunderbolt:

TBT Root Port Selektor:**Auto**

Thunderbolt Boot Support: **Enabled**

Security Level: **SL0 no security**

USB:

Legacy usb support: **enabled**

XHCI Handoff: **enabled**

Mass Storage driver support: **enabled**

Network

Network stack: **disabled**

Boot

Fast Boot: **Disabled link**

Windows 8/10 Features: **other OS**

Secure Boot: **disabled**