

# DX79TO Kernel PANic

Beitrag von „sido190“ vom 13. November 2022, 03:07

NVRAM ressting benutze, ich schon. und das mit denn github link werde ich mal testen.

Hier ist auch noch die Aktuelle OC EFI die ich gerade benutze.

EDIT:

Ich hab es geschafft das er nichtmehr mit kernel panic abschmiert abe trotzdem bootet er nicht, er freezt komplett jetzt.

```
AppleACPICPU: Processor Id=9 LocalApicId=9 Enabled
AppleACPICPU: Processor Id=10 LocalApicId=10 Enabled
AppleACPICPU: Processor Id=11 LocalApicId=11 Enabled
AppleACPICPU: Processor Id=12 LocalApicId=0 Disabled
AppleACPICPU: Processor Id=13 LocalApicId=0 Disabled
AppleACPICPU: Processor Id=14 LocalApicId=0 Disabled
AppleACPICPU: Processor Id=15 LocalApicId=0 Disabled
calling smp_policy_init for: IBSafetyNet
Security policy loaded: Safety net for Titan Machine (IBSafetyNet)
calling smp_policy_init for: DMFI
Security policy loaded: Apple Mobile File Integrity (DMFI)
calling smp_policy_init for: SandBox
Security policy loaded: SanDBalt sandBox policy (SandBox)
calling smp_policy_init for: Quarantine
Security policy loaded: Quarantine policy (Quarantine)
Copyright (c) 1982, 1986, 1989, 1991, 1993
The Regents of the University of California. All rights reserved.
MFC Framework successfully initialized
Using I/O buffer headers and IO240 cluster ID buffer headers.
Unsyncronized ITC for cpu 1: 0x000000007f2791c0, delta 0x0tr>
Unsyncronized ITC for cpu 2: 0x000000007f2e0320, delta 0x94262
Unsyncronized ITC for cpu 3: 0x000000007f31c2c0, delta 0x17c02
Unsyncronized ITC for cpu 4: 0x000000007f37c200, delta 0x0ptr>
Unsyncronized ITC for cpu 5: 0x000000007f380000, delta 0x0ptr>
Unsyncronized ITC for cpu 6: 0x000000007f333000, delta 0x0320
Unsyncronized ITC for cpu 7: 0x000000007f3c0000, delta 0x0ptr>
Unsyncronized ITC for cpu 8: 0x000000007f30334, delta 0x0ptr>
Unsyncronized ITC for cpu 9: 0x000000007f3007000, delta 0x0ptr>
Unsyncronized ITC for cpu 10: 0x000000007f3007000, delta 0x0ptr>
Unsyncronized ITC for cpu 11: 0x000000007f3007000, delta 0x0ptr>
ACPI Warning: GPE_1_07 has no implementation (DMFI: Version 0x20 Vector 64:07
IGPE1C: Version 0x20 Vector 00:11)
ACPI Warning: GPE_1_07 has no implementation (DMFI: Version 0x20 Vector 64:07
IGPE1C: Version 0x20 Vector 00:11)
ACPI: Executed 4 blocks of mobile-level executable DMFI code
ACPI: sleep status 53 54 55
pci: DevId 22:24:100 Aug 31 2020, flags 0x200000
MIO: Legacy shio 2
MTC: Only single DMFI bank (120 bytes)
MTC: Legacy ITC init: # failed to call parent 7
MIO: Legacy shio 2
AppleIntel
```

Hier ist ein Bild genau an der stelle wo es freezt.

[apfel-baum](#) schon kleiner vortschritt, soweit bin ich noch nie gekommen bei denn system 🤔