

Mal wieder kein Sleep in Ventura

Beitrag von „hackopti2“ vom 18. Dezember 2022, 17:16

gibt's vielleicht neue Erkenntnisse hierzu: EFI/Bootrom Failure after last point of entry to sleep

Code

1. 2022-12-16 11:17:10 +0100 Assertions PID 151(WindowServer) TimedOut UserIsActive "com.apple.iohideventsystem.queue.ticklenxevent service:IOHIDSystem pid:682 process:LogiMgrDaemon" 00:09:59 id:0x0x900009256 [System: PrevIdle DeclUser kDisp]
2. 2022-12-16 11:17:10 +0100 Assertions Summary- [System: PrevIdle] Using AC
3. 2022-12-16 11:17:10 +0100 Notification Display is turned off
4. 2022-12-16 11:17:10 +0100 Assertions PID 46210(blueoothd) Summary PreventUserIdleSystemSleep "com.apple.bluetooth.bluetooth.script" 00:00:10 id:0x0x100009042 [System: PrevIdle]
5. 2022-12-16 11:17:24 +0100 Assertions Kernel Idle sleep preventers: -None-
6. 2022-12-16 11:17:24 +0100 Assertions PID 0(kernel_task) Released Idle Sleep Preventer "IODisplayWrangler" id:0x0x0 [System: PrevIdle]
7. 2022-12-16 11:17:29 +0100 Assertions PID 46210(blueoothd) Released PreventUserIdleSystemSleep "com.apple.bluetooth.bluetooth.script" 00:00:30 id:0x0x100009042 [System: No Assertions]
8. 2022-12-16 11:17:29 +0100 Assertions PID 95(powerd) Created InternalPreventSleep "com.apple.powermanagement.darkwakelinger" 00:00:00 id:0x0xd0000942b [System: SRPrevSleep kCPU]
9. 2022-12-16 11:17:44 +0100 Assertions PID 95(powerd) TimedOut InternalPreventSleep "com.apple.powermanagement.darkwakelinger" 00:00:15 id:0x0xd0000942b [System: PrevIdle SRPrevSleep kCPU]
10. 2022-12-16 11:17:44 +0100 Sleep Entering Sleep state due to 'Idle Sleep':TCPKeepAlive=inactive Using AC (Charge:0%)
11. 2022-12-16 11:17:46 +0100 Wake Requests [*process=powerd request=UserWake deltaSecs=16262 wakeAt=2022-12-16 15:48:49 info="com.apple.alarm.user-visible-com.apple.CalendarNotification.EKTravelEngine.periodicRefreshTimer,483"]
12. 2022-12-16 11:17:46 +0100 PM Client Acks Delays to Sleep notifications: [com.apple.apsd is slow(1972 ms)]
13. 2022-12-16 11:53:29 +0100 ShutdownCause SMC shutdown cause: 5: Software initiated shutdown
14. 2022-12-16 11:53:29 +0100 HibernateStats hibmode=0 standbydelaylow=0 standbydelayhigh=0 0

15. 2022-12-16 11:53:29 +0100 Failure Failure during sleep: 0x0000001F : EFI/Bootrom
Failure after last point of entry to sleep

Alles anzeigen