

Installation of macOS Ventura on a Huananzhi x79+E5-2650V2 motherboard

Beitrag von „Steel_Leandro“ vom 24. Dezember 2022, 14:37

Code

1. Well, I already tried to put MacPro7,1 or iMacPro1,1 and put this kexts CryptexFixup.
- 2.
3. Restarts in the processor part.