

MSI X99A GAMING PRO CARBON - Ventura

Beitrag von „MeO-Style“ vom 31. Dezember 2022, 15:32

Da kommt folgendes...



```
BRAVIA
No option selected, verify only.
Usage: ControlMsrE2 <unlock | lock | interactive>

Looking up EFI_MP_SERVICES_PROTOCOL...
Checking MSR 0xE2 on all CPUs. Values must be 0F0E!!!
CPU00 has MSR 0xE2: 0x0000000000000402
Starting All APs to verify 0xE2 register...
CPU01 has MSR 0xE2: 0x0000000000000402
CPU02 has MSR 0xE2: 0x0000000000000402
CPU03 has MSR 0xE2: 0x0000000000000402
CPU04 has MSR 0xE2: 0x0000000000000402
CPU05 has MSR 0xE2: 0x0000000000000402
CPU06 has MSR 0xE2: 0x0000000000000402
CPU07 has MSR 0xE2: 0x0000000000000402
CPU08 has MSR 0xE2: 0x0000000000000402
CPU09 has MSR 0xE2: 0x0000000000000402
CPU10 has MSR 0xE2: 0x0000000000000402
CPU11 has MSR 0xE2: 0x0000000000000402
Done checking MSR 0xE2 register, compare the values printed!
This firmware has UNLOCKED MSR 0xE2 register!
Press any key.
```