

Critical Error den ich nicht ganz verstehen kann (Incompatible OpenRuntime r10, require r12)

Beitrag von „hema8193“ vom 3. Januar 2023, 11:06

Wie im Titel steht hält mir das System schon an bevor er etwas bootet. Es ist im TXT File dann der Hinweis "Incompatible OpenRuntime r10, require r12"

Ich habe die OpenRuntime vom OC nackten Ordner verwendet, Was muss ich hier machen?
Danke euch für die Hilfe:

Hier die LOG:

```
00:000 00:000 BS: Starting OpenCore application...
00:000 00:000 BS: Booter path - \EFI\BOOT\BOOTX64.EFI
00:000 00:000 OCFS: Trying to locate filesystem on 847A9B18 850D7518
00:000 00:000 OCFS: Filesystem DP - \EFI\BOOT\BOOTX64.EFI
00:000 00:000 BS: Trying to load OpenCore image...
00:000 00:000 BS: Relative path - EFI
00:000 00:000 BS: Startup path - EFI\OpenCore.efi (0)
00:000 00:000 BS: Fallback to absolute path - EFI\OC\OpenCore.efi
00:000 00:000 BS: Read OpenCore image of 991232 bytes
00:000 00:000 OCM: Loaded image at 8362EA98 handle
00:000 00:000 OCM: Loaded image has DeviceHandle 847A9B18 FilePath 8362F598 ours
DevicePath 8362F198
00:000 00:000 OCCPU: TSC Adjust 0
00:000 00:000 OCCPU: Known Model Core Crystal Clock Frequency 24000000Hz
00:000 00:000 OCCPU: CPUFrequencyFromART 2304000000Hz 2304MHz = 24000000 * 192 / 2
00:000 00:000 OC: Starting OpenCore...
00:000 00:000 OC: Booter path - EFI\OC\OpenCore.efi
```

00:000 00:000 OCFS: Trying to locate filesystem on 847A9B18 8362F598
00:000 00:000 OCFS: Filesystem DP - EFI\OC\OpenCore.efi
00:000 00:000 OC: Absolute booter path - EFI\OC\OpenCore.efi
00:000 00:000 OC: Storage root EFI\OC\OpenCore.efi
00:000 00:000 OCST: Missing vault data, ignoring...
00:000 00:000 OC: OcMiscEarlyInit...
00:000 00:000 OC: Loaded configuration of 14037 bytes
00:000 00:000 OC: Got 2 drivers
00:000 00:000 OC: Watchdog status is 1
00:106 00:106 OC: OpenCore DBG-088-2023-01-02 is loading in Optional mode (0/0)...
00:147 00:040 OC: Boot timestamp - 2023.01.03 10:58:27
00:187 00:039 OCCPU: MP services threads 16 (enabled 16) - Success
00:228 00:040 OCCPU: MP services Pkg 1 Cores 8 Threads 2 - Success
00:268 00:040 OCCPU: Found Intel(R) Core(TM) i9-9880H CPU @ 2.30GHz
00:308 00:040 OCCPU: Signature 906ED Stepping D Model 9E Family 6 Type 0 ExtModel 9
ExtFamily 0 uCode F0 CPUID MAX (16/80000008)
00:349 00:041 OCCPU: EIST CFG Lock 1
00:389 00:040 OCCPU: TSC Adjust 0
00:429 00:039 OCCPU: Known Model Core Crystal Clock Frequency 24000000Hz
00:470 00:040 OCCPU: CPUFrequencyFromART 2304000000Hz 2304MHz = 24000000 * 192 / 2
00:518 00:048 OCCPU: Timer address is 0 from Unknown INTEL
00:558 00:040 OCCPU: Failed to get FSBFrequency data using Apple Platform Info - Not Found
00:598 00:040 OCCPU: Intel TSC: 2304000000Hz, 2304MHz; FSB: 100173913Hz, 100MHz;
MaxBusRatio: 23
00:638 00:040 OCCPU: Detected Apple Processor Type: 10 -> 1009
00:679 00:040 OCCPU: CPUFrequencyFromTSC 0Hz 0MHz

00:719 00:040 OCCPU: CPUFrequency 2304000000Hz 2304MHz
00:759 00:040 OCCPU: FSBFrequency 100173913Hz 100MHz
00:799 00:039 OCCPU: Pkg 1 Cores 8 Threads 16
00:840 00:040 OC: OcLoadNvramSupport...
00:881 00:040 OCVAR: Locate emulated NVRAM protocol - Not Found
00:921 00:040 OCVAR: Setting NVRAM 4D1EDE05-38C7-4A6A-9CC6-4BCCA8B38C14:DefaultBackgroundColor - ignored, exists
01:035 00:113 OCVAR: Setting NVRAM 4D1FDA02-38C7-4A6A-9CC6-4BCCA8B30102:rtc-blacklist - Not Found
01:075 00:040 OCVAR: Setting NVRAM 7C436110-AB2A-4BBB-A880-FE41995C9F82:ForceDisplayRotationInEFI - Success
01:115 00:039 OCVAR: Setting NVRAM 7C436110-AB2A-4BBB-A880-FE41995C9F82:boot-args - ignored, exists
01:155 00:040 OCVAR: Setting NVRAM 7C436110-AB2A-4BBB-A880-FE41995C9F82:csr-active-config - ignored, exists
01:196 00:040 OCVAR: Setting NVRAM 7C436110-AB2A-4BBB-A880-FE41995C9F82:run-efi-updater - ignored, exists
01:236 00:040 OC: Current version is DBG-088-2023-01-02
01:276 00:040 OC: OcMiscMiddleInit...
01:316 00:040 OC: StorageHandle 847A9B18 with Disabled LauncherOption pointing to Default
01:357 00:040 OC: OcLoadUefiSupport...
01:397 00:039 OCAU: OcAudioInstallProtocols (0, 0)
01:437 00:040 OCAU: 4B228577-6274-4A48-82AE-0713A1171987 protocol - Not Found
01:478 00:040 OCAU: C32332DF-FC56-4FE1-9358-BA0D529B24CD protocol - Not Found
01:518 00:040 OCAU: F4CB0B78-243B-11E7-A524-B8E8562CBAFA protocol - Not Found
01:558 00:040 OCAU: 3224B169-EC34-46D2-B779-E1B1687F525F protocol - Not Found
01:624 00:065 OCAE: Builtin installed
01:664 00:039 OCRTC: Wake log is 0x53 0x42 83 0x48

01:704 00:040 OCEG: Discovered rotate NVRAM override to 0

01:744 00:039 OC: Automatic SB model j680 from model MacBookPro15,1

01:784 00:040 OC: Loading Apple Secure Boot with j680 (level 1)

01:827 00:042 OCABC: ALRBL 0 RTDFRG 0 DEVMMIO 1 NOSU 0 NOVRWR 0 NOSB 0 FBSIG 0
NOHBMAP 0 SMSLIDE 0 WRUNPROT 0

01:866 00:039 OCABC: FEXITBS 0 PRMRG 0 CSLIDE 0 MSLIDE 0 PRSRV 1 RBMAP 1 VMAP 0
APPLOS 0 RTPERMS 1 ARBAR -1

01:907 00:040 OCABC: Firmware has 8261008 free pages (542096 in lower 4 GB)

02:013 00:105 OCABC: Awaiting rendezvous with OpenRuntime r12

02:052 00:039 OC: RequestBootVarRouting 0

02:093 00:040 OC: Got 2 drivers

02:133 00:039 OC: Driver HfsPlus.efi at 0 () is being loaded...

02:187 00:053 OCABC: EfiBootRt candidate - <nil>

02:222 00:035 OCABC: IsEfiBootRt 0 (BP 1, Apple 0)

02:262 00:040 OCB: Arch filtering 0(37892)->83556018(37892) caps 4 - Success

02:303 00:040 OCABC: Recovering trashed GetMemoryMap pointer

02:343 00:039 OC: Driver HfsPlus.efi at 0 is successfully loaded!

02:383 00:039 OC: Driver HfsPlus.efi at 0 needs connection.

02:423 00:040 OC: Driver OpenRuntime.efi at 1 () is being loaded...

02:473 00:049 OCABC: EfiBootRt candidate - <nil>

02:508 00:035 OCABC: IsEfiBootRt 0 (BP 1, Apple 0)

02:549 00:040 OCB: Arch filtering 0(20484)->8355A018(20484) caps 4 - Success

02:594 00:045 OCABC: Recovering trashed GetMemoryMap pointer

02:630 00:035 OCABC: Incompatible OpenRuntime r10, require r12

[edit](#): Habe es schon rausgefunden! Ich habe die falschen Daten ausgetauscht.

Beste Grüße
Hema