


MacOS auf Matebook 13 2019 i5 (Mx250) Deutsche Anleitung?

Beitrag von „waldfee123“ vom 9. März 2023, 07:07

So... Es lag an der Secure Option im BIOS. Hab ich wohl überlesen oder nirgends als Info bekommen. Hab jetzt verschiedene EFIs getestet.

Die von Bluebyte crashed sehr schnell :



Die andere läuft ordentlich weit... Dann leuchtet die Tastatur kurz auf und es kommt das

```
ApplePS2Controller: Notification consumer published: ApplePS2Controller
ApplePS2Controller: Notification consumer published: ApplePS2Keyboard
IOHIDInterface(0x1000003b2): matching deferred by IOHIDEventDriver
000001.724053 HSB4@14400000: AppleUSBHostPort::enumerateDeviceComplete_block_invoke: enumerated 0x13d3/56c6/1807
VoodooPS2Trackpad: Identify TouchPad command failed
VoodooI2CPCIController::pci8086,9de8 Set PCI power state D0
VoodooI2CPCIController::pci8086,9de8 Publishing nub
VoodooI2CControllerDriver::pci8086,9de8 Probing controller
VoodooI2CControllerDriver::pci8086,9de8 Found valid Synopsys component, continuing with initialisation
VoodooI2CControllerDriver::pci8086,9de8 Got bus configuration values
VoodooI2CControllerDriver::pci8086,9de8 Publishing device nubs
VoodooI2CControllerDriver::pci8086,9de8 Found I2C device: ELAN962C
VoodooI2CDeviceNub::Got GPIO Controller! VoodooGPIOCannonLakeLP
IntelFirmware: send firmware payload done
IntelFirmware: Notify: Firmware download done
IntelFirmware: Notify: Device reboot done
IntelFirmware: Found device firmware ibt-17-16-1.ddc
IntelFirmware: Load DDC config: ibt-17-16-1.ddc 14
IntelFirmware: Load DDC config done
IntelFirmware: Firmware revision 0.1 build 20 week 53 2019
IntelFirmware: Clean up...
IntelFirmware: virtual void BtIntel::free()
IntelFirmware: virtual void USBDeviceController::free()
ACPI Warning: \_SB.PCI0.I2C0.TPD0.DSM: Argument #4 type mismatch - Found [Integer], ACPI requires [Package] (2016
VoodooGPIOCannonLakeLP: Registering hardware pin 0x1C for GPIO IRQ pin 0x23
VoodooGPIOCannonLakeLP: Successfully registered hardware pin 0x1C for GPIO IRQ pin 0x23
VoodooI2CHIDDevice:ELAN962C Device initiated reset accomplished
open by VoodooI2CPrecisionTouchpadHIDEventDriver 0x1000003cb (0x0)
open by AppleActuatorHIDEventDriver 0x1000003da (0x0)
BuildActDeviceEntry enter
AppleActuatorDevice::start Entered
BuildActDeviceEntry exit
open by AppleMultitouchTrackpadHIDEventDriver 0x1000003dc (0x0)
HID: Legacy shim 2
VoodooI2CPrecisionTouchpadHIDEventDriver:ELAN962C Putting device into Precision Touchpad Mode
HID: Legacy shim 2
ApplePS2Controller: Notification consumer published: VoodooI2CPrecisionTouchpadHIDEventDriver
```

Es passiert nichts.. Dann wird die Schrift pixelig und so ein durchgestrichener Kreis kommt...