

Ventura Plötzlich kein BT mehr

Beitrag von „byebye123“ vom 5. Juni 2023, 08:50

The following serves to enable bluetooth in macOS Ventura 13.4+ for Broadcom & Intel Bluetooth

1. Navigate to the NVRAM > Add > 7C436110-AB2A-4BBB-A880-FE41995C9F82 section in your config.plist file and add the two child items:

Key	Type	Value
bluetoothInternalControllerInfo	Data	00000000000000000000000000000000
bluetoothExternalDongleFailed	Data	00

2. Update BlueToolFixup from BrcmPatchRAM 2.6.7

3. Reboot and Reset NVRAM then boot again normally

The fix is now working for both Intel and Broadcom Bluetooth, but the official [acidanthera BrcmPatchRAM](#) needs to be updated first. A test version is available at Github here:

<https://github.com/acidanthera/BrcmPatchRAM/pull/28>

I attached the BrcmPatchRAM-2.6.7.zip to this post for reference.