

X99 Dual CPU erst Boot bei Installation Menu Bildschirm schwarz und Neustart

Beitrag von „MacGrummel“ vom 13. Juni 2023, 12:14

Du brauchst eine Anpassung für USB, am Besten einen USB-Kext. Die einfache Methode mit dem USBInjectAll.Kext über das Hackintool funktioniert ja mit BigSur leider nicht mehr richtig, auch wenn ich bis heute nicht verstanden habe, warum, bzw warum nicht..

Hast Du noch ein anderes Betriebssystem, das auf dem Rechner schon läuft?

P.S.:

Du solltest bei UEFI/APFS MinDate und MinVersion jeweils auf -1 einstellen. Nur damit werden ältere Systeme auch erkannt. Die Bezeichnung von 0 = Auto ist hier irreführend.

P.P.S.:

Und ich sehe grade in der Beschreibung für OC 093, dass jetzt der Quirk XhciPortLimit wieder funktionieren soll. Kannst es damit ja erstmal probieren.

19 hours ago
vandroiy2013
0.9.3
d52fc46


Compare

0.9.3 Latest

v0.9.3

- Added `--force-codec` option to `AudioDxe`, thx @xCuri0
- Downgraded additional warning message in normal operation of emulated NVRAM to info
- Disabled not present DVL0 device in SSDT-SBUS-MCHC by default, thx @stevezhengshiqi
- Added EFI mandated box drawing, block element and arrow characters to `Builtin` renderer console font
- Improved support for overlong menu entries and very narrow console modes in builtin picker
- Made `Builtin` text renderer ignore UI Scale, when required to ensure that text mode reaches minimum UEFI supported size of 80x25
- Added save and restore of text and graphics mode round tools and failed boot entries
- Updated out-of-range cursor handling to work round minor display issue in memtest86
- Added optional `--enable-mouse-click` argument to `CrScreenshotDxe` driver to additionally respond on mouse click
- Added `--use-conn-none` option to `AudioDxe` driver to discover additional usable output channels on some systems
- Added `PciIo` protocol override used to fix Aptio IV compatibility with Above 4G BARs, thx @xCuri0
- Fixed `AppleXcpmForceBoost` quirk on macOS 14
- Updated builtin firmware versions for SMBIOS and the rest
- Added `ConsoleFont` option to load custom console font for `Builtin` renderer
- Improved `XhciPortLimit` quirk on macOS 11 to 14

Contributors


xCuri0 and stevezhengshiqi

Assets 4

[OpenCore-0.9.3-DEBUG.zip](#) 8.89 MB 18 hours ago