

Hilfe bei: Hackintosh auf AMD System installieren

Beitrag von „fabiosun“ vom 16. Juni 2023, 10:30

if the ports work is a initial condition

different is to say if they are well mapped

Internal, external usb 2/3 Usb C and so on must be set properly

also if your AMD 6950xt has usb type c port could be a problem

if you like post an IOREG of your working system to see how USB ports are seen in it