

Ventura Plötzlich kein BT mehr

Beitrag von „Knecht“ vom 9. August 2023, 21:41

The descriptions are all a bit confusing, as I'm not sure what exactly needs to be done. I downloaded the latest release from <https://github.com/acidanthera/BrcmPatchRAM> and installed

BrcmPatchRAM3.kext

BrcmFirmwareData.kext and

BlueToolFixup.kext

And my Broadcom USB dongle works in 13.5 Ventura. But do I really need all three kexts? I changed or added nothing else to the config