

FUJITSU CELSIUS R930 WORKSTATION CHIPSET: INTEL® C602. (X79) E5-2697V2 MONTEREY WILL NOT BOOT

Beitrag von „apfel-baum“ vom 26. August 2023, 20:00

hello [kobiemexx2](#) ,

here you'll go - <https://dortania.github.io/Ope...ig-HEDT/ivy-bridge-e.html>

- i think the advise feature flag, should be necessary

- without the efi it would be quite bad to offer you help.

- is it a git efi or made by yourself?

- take a look at this tool - <https://github.com/ic005k/OCAuxiliaryTools/releases>

-this forum is an german forum so the most will offer you help in german. i don't know your mother tounge, so the answer is currently in english.

lg 😊