

EFI für Gigabyte Aorus Gaming 7 & Threadripper 1950x X399

Beitrag von „fabiosun“ vom 27. August 2023, 10:44

if you see UEFI in your [bios settings](#) you are fine

legacy boot is worst to start

you could also have a mixed situation but UEFI should be your choice

Your system is a very good system and with a little effort you can install latest OSX if you like

edit

config plist based on Hecantomb's EFI

i have corrected kernel patches for your core count and changed SMBios to MacPro7,1 (if you like to try Big Sur, Monterey/Ventura or Sonoma)