

# MacOS Ventura Blackscreen

Beitrag von „fabiosun“ vom 10. September 2023, 18:24

hi [Fyynnn](#) are we talking about Asus Rog Strix B550F Gaming WIFI II?

if so, npci bootarg shouldn't be useful

Search in bios 4G and set to ON

Also UEFI ON /CSM OFF

I will also disable all kext not useful to boot in your rig

You have intel Ethernet ( i think I225) and you are using a kext for realtek ethernet in your EFI

Are Usb mapping kexts done exactly for your motherboard?