

Bin kurz vorm Hackintosh Ausstieg - STaändig neue Probleme - Aktuell Aussetzer auf Desktop und besonders stark bei Browser Video Wiedergabe

Beitrag von „Wolfe“ vom 23. September 2023, 13:10

Das Smbios iMac20,2 passt schon mal zu der CPU 10900kf, laut Dortania.

Ist dein Bios so eingestellt, wie von [Dortania empfohlen](#)?

Intel BIOS settings

- Note: Most of these options may not be present in your firmware, we recommend matching up as closely as possible but don't be too concerned if many of these options are not available in your BIOS

#Disable

- Fast Boot
- Secure Boot
- Serial/COM Port
- Parallel Port
- VT-d (can be enabled if you set `DisableIoMapper` to YES)
- Compatibility Support Module (CSM) (**Must be off in most cases, GPU errors/stalls like `gIO` are common when this option is enabled**)
- Thunderbolt (For initial install, as Thunderbolt can cause issues if not setup correctly)
- Intel SGX
- Intel Platform Trust
- CFG Lock (MSR 0xE2 write protection)(**This must be off, if you can't find the option then enable `AppleXcpmCfgLock` under Kernel -> Quirks. Your hack will not boot with CFG-Lock enabled**)

#Enable

- VT-x
- Above 4G Decoding
 - 2020+ BIOS Notes: When enabling Above4G, Resizable BAR Support may become available on some Z490 and newer motherboards. Please ensure that Booter -> Quirks -> ResizeAppleGpuBars is set to 0 if this is enabled.
- Hyper-Threading
- Execute Disable Bit
- EHCI/XHCI Hand-off
- OS type: Windows 8.1/10 UEFI Mode (some motherboards may require "Other OS" instead)
- [DVMT](#) Pre-Allocated(iGPU Memory): 64MB or higher
- SATA Mode: AHCI