

## **In Arbeit** HP ProBook 650 G1

**Beitrag von „benos23“ vom 2. Januar 2024, 19:11**

[Max](#)

I've also encounter the after sleeping problem too on Sonoma. Looks like it's due to the OCLP system patch. I didn't find any solution, I reinstalled Monterey where everything work great without system patches

And For **THOSE SUFFERING FOR SOME APPS STORE APPS CRASHING AFTER DISABLING AMFI & SIP ON VENTURA AND SONOMA**, try this boot args : `ipc_control_port_options=0`