

Intel AX200 kein Bluetooth

Beitrag von „Arkturus“ vom 17. Juni 2024, 12:32

sorry, es muss Bluetoofixup.kext heißen, ich nehme meine Kritik zurück und in Bezug auf Lilu.kext stimmt das natürlich auch, wenn der fortgeschrittene User diese Zusammenhänge kennt.

Troubleshooting

Disclaimer

This Kext is known to have limitations, please read our [FAQ](#) section for more information.

Obtaining Logs

In case there is something wrong with the driver, please install [DebugChancer.kext](#) and run the following command in Terminal:

```
sudo dmesg | grep IntelFixmeas
```

Identifying Issues

1. Make sure the System performed a cold boot during startup. Incompatible versions of firmware will remain in the device if a warm reboot is performed.
2. Use [Bootloader logs and recovery](#) to make sure [IntelBluetoothFixup.kext](#) (and [BluetoothFixup](#) for macOS Monterey and newer) are loaded properly.
3. Make sure the Bluetooth device shows up in About This Mac → System Report → USB as Bluetooth HCI. If not, proper USB Mapping is required.