

# Dell Latitude E7450 i7 Ventura

Beitrag von „Arkturus“ vom 8. Juli 2024, 11:15

hier kommst du zu den Anweisungen zum WEG, aber das Bootarg nannte ich ja schon.



Wenn Das nicht reicht, kommst du mit den Framebuffern schon weiter, die Quellen hast Du ja gefunden.

hier steht es doch, was willst Du noch?

Looking closer, we see that the HDMI port was actually listed as a DisplayPort. This is where WhateverGreen's patching mechanisms come into play.

Since the incorrect port was located at AppleIntelFramebuffer@1, this is port 1. Next we'll enable WhateverGreen's patching mechanism for con0, and then set the connector type to HDMI. To do this, we set the following Properties under `DeviceProperties -> AAE -> PciRoot(0x0)/Pci(0x2,0x0)`:

- `FrameBufferPatchEnable = 0x00000001`
  - = Enables WhateverGreen's patching mechanism
- `FrameBufferPatchEnable = 0x00000001`
  - = Enables WhateverGreen's patching on con0
- `FrameBufferPatchType = 0x00000001`
  - = Sets the port to HDMI (0x00, 0x00, 0x00)

Note: Remember to replace the `con0` in both patches with `con1` to reflect the port that we want fixed, then set the values as listed above.

