

Ventura Ryzen 5: L Ä U F T !

Beitrag von „Bob-Schmu“ vom 28. Juli 2024, 21:57

[Zitat von wu ming](#)

Die Kiste schaltet sich von selbst aus. Friert ein.

DANGER
NEVER use both `itlim.kext` and `AirportItlim.kext` at the same time.
Never install Kernel Extensions into `/Library/Extensions` or `/System/Library/Extensions`. Take your own risk when you do so.

What additional steps should I do to make Bluetooth work on macOS Monterey and newer

1. Install `IntelBTPatch.kext` (Depends on Lilu v1.6.2 or newer)
2. Make sure `IntelBluetoothFirmware.kext` v2.2.0 or newer is used.
3. **Remove/Exclude** `IntelBluetoothInjector.kext` for macOS Monterey and newer from the Bootloader's config
4. Install `BlueToolFixup.kext` from [acidanthera@rcmPatchRAM](#)