

Problem mit Trim-Timeout bei Samsung SSD seit 14.5 gelöst?

Beitrag von „Arkturus“ vom 22. September 2024, 14:15

Ja, danach gehts weiter:

Note: The failsafe value -1 indicates that this patch will not be applied, such that `apfs.kext` will remain

untouched.

Note 2 : On macOS 12.0 and above, it is no longer possible to specify trim timeout. However, trim can be disabled

by setting 0.

Note 3 : Trim operations are only affected at booting phase when the startup volume is mounted. Either specifying

timeout, or completely disabling trim with 0, will not affect normal macOS running.