

# Probleme mit erster eigener EFI

Beitrag von „ST3R30“ vom 15. März 2025, 14:24

[Triso01](#)

Probier's mal mit dem Standard-Framebuffer-patch:

▼ PciRoot(0x0)/Pci(0x2,0x0)	‡ Dictionary	3 key/value pairs
AAPL,ig-platform-id	‡ Data	<00001219>
framebuffer-patch-enable	‡ Data	<01000000>
framebuffer-stolenmem	‡ Data	<00003001>

Code

1. <dict>
2. <key>PciRoot(0x0)/Pci(0x2,0x0)</key>
3. <dict>
4. <key>AAPL,ig-platform-id</key>
5. <data>AAASGQ==</data>
6. <key>framebuffer-patch-enable</key>
7. <data>AQAAAA==</data>
8. <key>framebuffer-stolenmem</key>
9. <data>AAAwAQ==</data>
10. </dict>