

Erledigt

Probleme beim Hackintosh 10.8.5 / HD4000 us.

Beitrag von „TuRock“ vom 20. Oktober 2013, 03:03

versuche mal das hier (in org.chameleon.boot.plist eintragen) :

XML

1. <?xml version="1.0" encoding="UTF-8"?>
2. <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
3. <plist version="1.0">
4. <dict>
5. <key>EthernetBuiltIn</key>
6. <string>Yes</string>
7. <key>Kernel</key>
8. <string>mach_kernel</string>
9. <key>Kernel Flags</key>
10. <string>PCIRootUID=0</string>
11. <key>DropSSDT</key>
12. <string>Yes</string>
13. <key>GraphicsEnabler</key>
14. <string>No</string>
15. <key>Timeout</key>
16. <string>1</string>
17. <key>UseKernelCache</key>
18. <string>Yes</string>
19. <key>device-properties</key>
20. <string>
8800000001000000010000007c0000000200000002010c00d041030a000000000101060000027fff040
</string>
21. <key>Graphics Mode</key>
22. <string>1920x1080x32</string>
23. </dict>
24. </plist>

Alles anzeigen