

Erledigt OZ 1669M and HD7970

Beitrag von „veranyon“ vom 10. Dezember 2015, 11:55

Hi, people.

I can't speak German. Russian only and few English.

OZ [Mod für das Z77-DS3H Rev.1.x](#) for rev 1.0. I have rev. 1.0 mb.

md5 of oz bin = b3008b962b28c582342f58ebcd5a8f9f (

Code

1. md5 /Volumes/home/iron/Downloads/Z77DS3H_OZ_1669_M.F9
2. MD5 (/Volumes/home/iron/Downloads/Z77DS3H_OZ_1669_M.F9) =
b3008b962b28c582342f58ebcd5a8f9f

)

Before 1669M I use 1479 one [Mod für das Z77-DS3H Rev.1.x](#). When use 1479 one that I hadn't any problems. video, audio etc. As soon as I go to 1669M ([Mod für das Z77-DS3H Rev.1.x](#)) I get problem with video (amd hd7970). There are no transparency effects (capitan, ml etc) as symptoms of problem. Also I'm watching that a computer was boot, the emblem of apple is bigger by resolution when it had been under oz 1479.

Also I made a such one:

Code

1. sudo nvram 1F8E0C02-58A9-4E34-AE22-2B63745FA101:AtiFramebuffer="Hamachi"

- no results. - checking:

Code

1. macpro:~ iron\$ sudo nvram 1F8E0C02-58A9-4E34-AE22-2B63745FA101:AtiFramebuffer
2. 1F8E0C02-58A9-4E34-AE22-2B63745FA101:AtiFramebuffer Hamachi
3. macpro:~ iron\$ sudo nvram 1F8E0C02-58A9-4E34-AE22-2B63745FA101:DisableAtiInjection
4. 1F8E0C02-58A9-4E34-AE22-2B63745FA101:DisableAtiInjection %00

try it with google (ozmosis 1669m "hd7970" in google search) - nothing.
People. Help, please. What must I read that decide that problem? I had diff OzmosisDefaults from 1479 and 1669M and didn't find any general differences. serial, model etc.

Beitrag von „veranyon“ vom 10. Dezember 2015, 13:02

Solved.

Go to accessibility > Display > unchecking "Reduce Transparency" one.

In total:

1. sudo nvram 1F8E0C02-58A9-4E34-AE22-2B63745FA101:AtiFramebuffer="Hamachi"
2. reboot
3. Go to accessibility > Display > unchecking "Reduce Transparency" one.

Beitrag von „al6042“ vom 10. Dezember 2015, 18:11

Great...

Thank you for the information.

I love it when issues and problems are solved be themselves... 😊