

Erledigt

Ozmosis can not load any files in the Oz directory

Beitrag von „xlazy.xyz“ vom 15. April 2017, 13:30

Hello,

I have a trouble, can not load any files in the Oz directory, kext, plist or aml. There is only one hard disk on the computer , and only GUID HFS+ file system in the disk.Oz directory is automatically created by the BIOS. The ROM is Z97XUD3H_iMac14.1_F9_Sierra2.rom.zip. How can I fix it ? Thanks !

By the way,How can I extract FFS file ? I want to put OzmosisDefaults.ffa into Oz directory .Rename it to plist and edit it?


Now everything works properly.

FAST BOOT MUST BE SET DISABLE !!!
FAST BOOT MUST BE SET DISABLE !!!
FAST BOOT MUST BE SET DISABLE !!!



Beitrag von „griven“ vom 15. April 2017, 13:44


It's not enough to simply extract the ffs file and rename it. Use UEFI Tool and extract the Body of it's raw section just like that:



Beitrag von „xlazy.xyz“ vom 15. April 2017, 14:03

[Zitat von griven](#)

It's not enough to simply extract the ffs file and rename it. Use UEFITool and extract the Body of it's raw section just like that:



[Quote](#)

Thanks! I will learn and try it. Now I want to load DSDT to drive my sound card. Use Clover boot, add AppleALC.kext and CodecCommander.kext in the EFI directory, and then set Audio Inject = 1, the sound card can be used normally. But I found that I could not load anything in the Oz directory. How can i solve this trouble?Could you help me ?Please !

Beitrag von „griven“ vom 15. April 2017, 14:24

Why Clover if you use OZ? Here is a patched DSDT with LayoutID set to LayoutID1: [DSDT.aml](#) place it on your EFI Partition under Efi/Oz/Acpi/Load also place AppleALC-OZM.kext taken from here [AppleALC - der dynamische AppleHDA Patcher - immer aktuell](#) and Lilu.kext taken from here: [Lilu - Generic kext patcher \(neue Grundlage für AppleALC 1.1.x und Shiki 2.x.x\)](#) into /Efi/Oz/Darwin/Extensions/Common/ and thats it sound should work afterwards.

Beitrag von „xlazy.xyz“ vom 15. April 2017, 15:23

[Zitat von griven](#)

Why Clover if you use OZ? Here is a patched DSDT with LayoutID set to LayoutID1: [DSDT.aml](#) place it on your EFI Partition under Efi/Oz/Acpi/Load also place AppleALC-OZM.kext taken from here [AppleALC - der dynamische AppleHDA Patcher - immer aktuell](#) and Lilu.kext taken from here: [Lilu - Generic kext patcher \(neue Grundlage für AppleALC 1.1.x und Shiki 2.x.x\)](#) into /Efi/Oz/Darwin/Extensions/Common/ and thats it sound should work afterwards.

Once, I used Clover.

I have placed the files on the right dir , and I place AppleIntelE1000e.kext on /efi/oz/darwin/extensions/common/ for a test. AppleIntelE1000e.kext can not load.

Now I will delete the Oz dir and then reflash the rom ,maybe it will work afterwards?