

Erledigt

Thunderbolt problem?

Beitrag von „Extreme“ vom 16. Mai 2020, 13:21

Hi!

I used the wonderful DSM2 guide to install Catalina and to optimize the post installation. Everything works except thunderbolt. When I start catalina and check the info menu on this mac / system report / PCI no thunderbolt entry is read. Is it normal or there is some problem. I specify that on windows 10 thunderbolt works perfectly.

I attach the Efi in use and my ioreg.

Thanks for helps.

My hardware:

Anidees AI Crystal XL AR 3

Asus WS X299 SAGE/10G

Intel Core i9-7980XE

Noctua NH-U12A

AMD Radeon™ VII

Crucial Ballistic Sport 3200 Mhz 128 GB

Gigabyte GC-TITAN RIDGE

caldigit ts3 plus

Sabrent 1TB Rocket NVMe PCIe M.2 2280 - macOS Catalina


Sabrent 1TB Rocket NVMe PCIe M.2 2280 - Windows 10

Download EFI:

<http://www.mediafire.com/file/mon1kr16bazs9pq/EFI.zip/file>

Download ioreg:

http://www.mediafire.com/file/...ac_Pro_di_Enrico.zip/file



Beitrag von „DSM2“ vom 17. Juli 2020, 07:40

Check the Guide again, everything necessary is already described there and attached for downloading. You have to adapt the Thunderbolt SSDT to your Setup if the path is different. For comparison use ioreg.