

# Chuji Corebook X

Beitrag von „KMac“ vom 12. Juli 2021, 20:15



Quelle: store.chuji.com

## CHUWI Corebook X

- i5-8259U (Coffee Lake U)
- Intel Iris Plus 655
- 8GB RAM DDR4 2400MHz (SK Hynix verlötet) + 8GB DDR4 2400MHz (Crucial, nachgerüstet - Gehäuse muss aufgeschraubt werden)
- 512GB Kingston M.2-SSD (kein 2.Steckplatz vorhanden - wird bei Gelegenheit getauscht)
- Audio Realtec ALC897
- Intel Dual Band AC-7265
- SYNA3602 Trackpad
- SMBios: MacbookPro15,2
- OC 0.7.1

Seriennummer usw. muss generiert und entsprechend eingetragen werden; itlwm.kext und IntelBluetoothFirmware.kext müssen im KEXT-Ordner eingefügt werden (der EFI -Ordner war sonst zum Hochladen zu groß).

Was funktioniert: Sound, Keyboard, Trackpad, Wifi, Bluetooth, Batterie, Shutdown, Restart, Sleep inkl. Lid-close, Ausgabe auf externen Monitor mittels USB-C auf DP Adapterkabel

todos: BrightnessKeys, Cardreader?,...

Probeweise war auch schon Big Sur 11.5 und Monterey beta installiert - beides lief ebenfalls ohne Probleme. Bin aber momentan auf Catalina.

---

### **Beitrag von „matteolidoni“ vom 6. Oktober 2021, 23:05**

Hello!

I am in a strange situation, I cannot get the WiFi to work. (Corebook 14" i4 8259u)

kext loads, but it doesn't work.

Checking with Hackintool my corebook has

realtek 8821CE

( not compatible)

but it should have an intel AC7265

I am wrong?

---

### **Beitrag von „Frabelo“ vom 22. Dezember 2022, 04:49**

So, you solv this? I maded work with itlwm.kext and control panel. But my Corbeook crashes with intensive video processing.