

Chuji Corebook X

Beitrag von „KMac“ vom 12. Juli 2021, 20:15



Quelle: store.chuwi.com

CHUWI Corebook X

- i5-8259U (Coffee Lake U)
- Intel Iris Plus 655
- 8GB RAM DDR4 2400MHz (SK Hynix verlötet) + 8GB DDR4 2400MHz (Crucial, nachgerüstet - Gehäuse muss aufgeschraubt werden)
- 512GB Kingston M.2-SSD (kein 2.Steckplatz vorhanden - wird bei Gelegenheit getauscht)
- Audio Realtec ALC897
- Intel Dual Band AC-7265
- SYNA3602 Trackpad
- SMBios: MacbookPro15,2
- OC 0.7.1

Seriennummer usw. muss generiert und entsprechend eingetragen werden; itlwm.kext und IntelBluetoothFirmware.kext müssen im KEXT-Ordner eingefügt werden (der EFI -Ordner war sonst zum Hochladen zu groß).

Was funktioniert: Sound, Keyboard, Trackpad, Wifi, Bluetooth, Batterie, Shutdown, Restart, Sleep inkl. Lid-close, Ausgabe auf externen Monitor mittels USB-C auf DP Adapterkabel

todos: BrightnessKeys, Cardreader?,...

Probeweise war auch schon Big Sur 11.5 und Monterey beta installiert - beides lief ebenfalls ohne Probleme. Bin aber momentan auf Catalina.

Beitrag von „matteolidoni“ vom 6. Oktober 2021, 23:05

Hello!

I am in a strange situation, I cannot get the WiFi to work. (Corebook 14" i4 8259u)

kext loads, but it doesn't work.

Checking with Hackintool my corebook has

realtek 8821CE

(not compatible)

but it should have an intel AC7265

I am wrong?

Beitrag von „Frabelo“ vom 22. Dezember 2022, 04:49

So, you solv this? I maded work with itlwm.kext and control panel. But my Corbeook crashes with intensive video processing.