

Anfrage aus dem HWC - HP Elite 8300 SFF

Beitrag von „kurtper“ vom 29. November 2021, 23:24

Anfrage an msart

[Zitat von iPhoneTruth](#)

Besten Dank!

Ich habe meine EFI mit Deiner ssdt.aml und Deiner USBPorts.kext bestückt, und dann die config.plist noch mit Deiner verglichen und angepasst. Damit funktioniert es jetzt.

Da sagt man doch glatt



Alles anzeigen

Code

1. Hallo!!
- 2.
3. Ich habe genau das gleiche Setup in "Big Sur" und möchte auf "Monterey" upgraden. hast du es geschafft? Könnten Sie EFI teilen?
- 4.
5. Vielen Dank!
- 6.
7. Sorry für die Übersetzung

Beitrag von „GoodBye“ vom 13. Dezember 2021, 17:17

[kurtper](#)

Hi and welcome to the Forum.

"Better put the NEW EFI on a USB Stick and boot from it"

"Make a Backup"

In Bios deactivate Internal USB Hub and PCI as PCIe4 Slot.

there is a downloadable EFI in the Hardware Forum for that HP8300 SFF with WX4100 aka RX560 dedicated Grafik Card.

For me to get Monterey and HW Accel. HVEC and H265 i hat to choose iMacPro SMBIOS.

For Monterey there are also SMBIOS without the Mac T2 Chip, where you do not have to get SecureBootModel configured, but i would do it anyway.

You can download the EFI here for the HP8300, it is with SMBIOS MacPro6,1 and should run with just enter SMBIOS Serial you generate.

In Order to use the iMacPro1,1 EFI get ProperTree and edit config.plist:

You have to generate a Serial for iMacPro1,1 SMBIOS and fill in.

Enter for iMacPro "J137" in config.plist under SecureBootModel (it's inside)

Enter in Terminal:

```
python3 -c 'import secrets; print (secrets.randbits (64)) '
```

the Number it generates you have to Enter in config.plist under

ApECID

boot into recovery and:

code

Run this command after setting your ApECID value

Replace Macintosh HD with your HD Name

open Terminal and run:

```
bless --folder "/" Volumes / Macintosh HD / System / Library / CoreServices" --bootefi --personalize
```

Reboot and Update or Install on Second HD should run.