

# GA H97-D3H-CF Diverse Fehlermeldungen

Beitrag von „MatsOL“ vom 11. Februar 2022, 10:41

Moin Ihr lieben ,

ich möchte gerne auf meinem Desktop Big Sur zum laufen bekommen . Installation hat geklappt bis jetzt geht das Netzwerk nicht .

Leider ist Englisch nicht meine Muttersprache und ich bekomme die Configuration von OpenCore einfach nicht hin .

Ich kann leider auch nicht mehr sagen wo ich die EFI her habe aber damit lief die Installation . Seriennummer etc habe ich angepasst .


Vielleicht kann jemand meine EFI Fixen ?

Vielen Dank für eure Hilfe

GA H97-D3H-CF

Intel(R) Core(TM) i5-4690 CPU @ 3.50GHz

Beim Booten kommen folgende Fehler :



```
CS: No schema for Base at 0 index, context <Patch>!  
OCS: No schema for BaseSkip at 1 index, context <Patch>!  
OCS: No schema for Base at 0 index, context <Patch>!  
OCS: No schema for BaseSkip at 1 index, context <Patch>!  
OCS: No schema for SyncTableIds at 5 index, context <Quirks>!  
OCS: No schema for ForceBooterSignature at 8 index, context <Quirks>!  
OCS: No schema for ProvideCurrentCpuInfo at 16 index, context <Quirks>!  
OCS: No schema for CustomKernel at 0 index, context <Scheme>!  
OCS: No schema for Flavour at 4 index, context <Entries>!  
OCS: No schema for AllowToggleSip at 2 index, context <Security>!  
OCS: No schema for AdviseFeatures at 0 index, context <Generic>!  
OCS: No schema for AppleInput at 1 index, context <UEFI>!  
OCS: No schema for ResetTrafficClass at 6 index, context <Audio>!  
OCS: No schema for GopPassThrough at 4 index, context <Output>!  
OCS: No schema for AppleEg2Info at 3 index, context <ProtocolOverrides>!  
OCS: No schema for ActivateIpetSupport at 0 index, context <Quirks>!  
OCS: No schema for EnableVectorAcceleration at 2 index, context <Quirks>!  
OCS: No schema for ForgeEFISupport at 4 index, context <Quirks>!  
OCS: No schema for ReloadOptionRom at 7 index, context <Quirks>!
```

Kext Updater meldet Folgende Fehler :

OCS: Missing key ResizeAppleGpuBars, context <Quirks>!  
OCS: Missing key PointerPollMask, context <AppleInput>!  
OCS: Missing key PointerPollMax, context <AppleInput>!  
OCS: Missing key PointerPollMin, context <AppleInput>!  
OCS: No schema for AudioOut at 2 index, context <Audio>!  
OCS: No schema for MinimumVolume at 4 index, context <Audio>!  
OCS: No schema for VolumeAmplifier at 8 index, context <Audio>!  
OCS: Missing key AudioOutMask, context <Audio>!  
OCS: Missing key DisconnectHda, context <Audio>!  
OCS: Missing key MaximumGain, context <Audio>!  
OCS: Missing key MinimumAssistGain, context <Audio>!  
OCS: Missing key MinimumAudibleGain, context <Audio>!  
OCS: Couldn't get array serialized at 0 index!  
OCS: Couldn't get array serialized at 1 index!  
OCS: Couldn't get array serialized at 2 index!  
OCS: Couldn't get array serialized at 3 index!  
OCS: Missing key ReconnectGraphicsOnConnect, context <Output>!  
OCS: Missing key UIScale, context <Output>!  
OCS: Missing key EnableVmx, context <Quirks>!  
OCS: Missing key ForceOcWriteFlash, context <Quirks>!  
OCS: Missing key ResizeGpuBars, context <Quirks>!

Serialisation returns 21 errors!

Booter->Quirks->ProvideCustomSlide is enabled, but OpenRuntime.efi is not loaded at UEFI->Drivers!

Booter->Quirks->EnableWriteUnprotector is enabled, but OpenRuntime.efi is not loaded at UEFI->Drivers!

CheckBooter returns 2 errors!

UEFI->Quirks->RequestBootVarRouting is enabled, but OpenRuntime.efi is not loaded at UEFI->Drivers!

CheckUefi returns 1 error!

Completed validating /Volumes/EFI/EFI/OC/config.plist in 2 ms. Found 24 issues requiring attention.

---

### **Beitrag von „Dr. Moll“ vom 11. Februar 2022, 11:09**

Moin,

Ich habe mal deine Config mit Ocat (Version 0.7.7) geöffnet und da werden ebenfalls etliche Fehler angezeigt. Deine verwendeten Kexte und Treiber scheinen nicht aktuell zu sein. Nach dem Updaten und erneuten validieren waren die Fehlermeldungen verschwunden.

Vielleicht versuchst du das mal.

Viel Erfolg

---

### **Beitrag von „MatsOL“ vom 11. Februar 2022, 11:24**



Danach noch mal links daneben schauen, ob noch was angemockert wird.

mit der neuen EFI weiter testen.

Viel Erfolg

---

**Beitrag von „MatsOL“ vom 11. Februar 2022, 14:05**

Super vielen lieben dank für die Erklärung werde es gleich testen .